LAND CAPABILITY ASSESSMENT ONSITE DOMESTIC WASTEWATER MANAGEMENT

Updated: May 2019



A Land Capability Assessment (LCA) is a written report that assesses the various aspects of a site and determines the capability of the land to sustain a wastewater system.

Central Goldfields Shire Council will be assessing LCAs received using both the Code of Practice Onsite Wastewater Management (EPA Publication 891.4) and the Victorian Land Capability Assessment Framework (VLCA – 2nd edition January 2014). Council's Environmental Health Unit are taking this approach to ensure consistency in the quality of LCAs received.

Central Goldfields Shire Council does not actively recommend or endorse any of the consultants listed and will not be held responsible for any issues that may arise due to an inadequate LCA being prepared, or any costs (financial or other) that may be incurred during the land capability assessment process.

If you have any queries about the LCA and the Onsite Domestic Wastewater Application process, please contact the Environmental Health Officer at Central Goldfields Shire Council on 5461 0647. Further information can also be obtained from the EPA Victoria website at www.epa.vic.gov.au

NB. There are other Consultants, not specifically listed who may also be able to prepare an acceptable LCA. Applicants are welcome to pursue other consultants not specifically listed below which may be found in the yellow pages (soil testing and investigations).

22 Nolan Street / PO Box 194, Maryborough VIC 3465 • Customer Service: 03 5461 0610 • Email: mail@cgoldshire.vic.gov.au

LAND CAPABILITY ASSESSMENT ONSITE DOMESTIC WASTEWATER MANAGEMENT

Updated: May 2019



The following list of consultants who prepare (LCAs) is provided for the convenience of developers, land owners and prospective landowners.

BENDIGO VIC 3550 Michael Brady, BSE Consulting Level 3, 77 Moorabool St GEELONG VIC 3220 Colin McClelland & Associates Ph. 03 5333 3030 201 Armstrong Street North BALLARAT VIC 3350 EHPIC Consulting Group 104 Wills Street BENDIGO VIC 3550 Geotechnical Testing Services Ph. 5441 4881 PO Box 555 GOLDEN SQUARE VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) 13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting Ph. 5221 5776 Email: luke@edwardsenvironmental.com.au Email: luke@edwardsenvironmental.com.au Ph. 5221 5776 Email: admin@bseconsulting.com.au Email: mail@colinmcclelland.com.au Email: contact@chpic.com.au Benall: contact@chpic.com.au Ph. 5441 4881 Pa. 5441 5089 Fax. 5441 4881 Ph. 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph. 5439 3511 Po Box 686 Mob: 0419 189 879 STRATHFIELDSAYE VIC 3074 Paladin White Pty Ltd Ph. 5439 3511 Po Box 686 SUNBURY VIC 3429 Email: jared@groundscience.com.au Phil Jeffery, PEJ Consulting Ph. 9336 1693 Mob: 0412 120 448 EAST KEILOR VIC 3033 Saunders Consulting Group Ph: 5229 0972 Email: info@soiltest.com.au WEST GEELONG VIC 3218	Edwards Environmental	Ph: 0413 066 065
Michael Brady, BSE Consulting Level 3, 77 Moorabool St GEELONG VIC 3220 Colin McClelland & Associates 201 Armstrong Street North BALLARAT VIC 3350 EHPIC Consulting Group 104 Wills Street BENDIGO VIC 3550 Geotechnical Testing Services Ph. 5441 4881 PO Box 555 GOLDEN SQUARE VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) 13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting Ph. 5229 0972 47 Pakington St Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Email: mail@colinmcclelland.com.au Email: contact@ehpic.com.au Ph. 5441 4881 Fax. 5441 5089 Col DEN SQUARE VIC 3555 Ground Science Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au THOMASTOWN VIC 3074 Pl. 5439 3511 PO Box 686 Mob: 0419 189 879 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Ph. 9336 1693 Mob: 0412 120 448 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting Ph. 9336 1693 Mob. 0412 120 448 EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Email: info@soiltest.com.au	10 Garsed Street	Email: luke@edwardsenvironmental.com.au
Michael Brady, BSE Consulting Level 3, 77 Moorabool St GEELONG VIC 3220 Colin McClelland & Associates 201 Armstrong Street North BALLARAT VIC 3350 EHPIC Consulting Group 104 Wills Street BENDIGO VIC 3550 Geotechnical Testing Services Ph. 5441 4881 PO Box 555 GOLDEN SQUARE VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) 13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting Ph. 5229 0972 47 Pakington St Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Email: mail@colinmcclelland.com.au Email: contact@ehpic.com.au Ph. 5441 4881 Fax. 5441 5089 Col DEN SQUARE VIC 3555 Ground Science Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au THOMASTOWN VIC 3074 Pl. 5439 3511 PO Box 686 Mob: 0419 189 879 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Ph. 9336 1693 Mob: 0412 120 448 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting Ph. 9336 1693 Mob. 0412 120 448 EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Email: info@soiltest.com.au	DEVIDIGO MICATES	
Level 3, 77 Moorabool St GEELONG VIC 3220 Colin McClelland & Associates 201 Armstrong Street North BALLARAT VIC 3350 EHPIC Consulting Group 104 Wills Street BENDIGO VIC 3550 Geotechnical Testing Services Ph. 5441 4881 PO Box 555 Fax. 5441 5089 GOLDEN SQUARE VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) 13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd PD Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting Ph. 5229 0972 47 Pakington St Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Email: admin@bseconsulting.com.au Ph. 0 35333 3030 Email: admin@bseconsulting.com.au Ph. 0 45 5333 3030 Email: admin@bseconsulting.com.au Email: mail@colinmcclelland.com.au Email: admin@bseconsulting.com.au Ph. 0 44 4881 Email: admin@bseconsulting.com.au Ph. 946 4617 Mob. 0418 898 Email: admin@bseconsulting.com.au Ph. 5439 351 Mob: 0419 189 879 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Ph. 9336 1693 Mob: 0412 120 448 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting Ph. 9336 1693 Mob. 0412 120 448 EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Email: info@soiltest.com.au		DI FOOT FEE(
GEELONG VIC 3220 Ph. 03 5333 3030 201 Armstrong Street North Email: mail@colinmcclelland.com.au BALLARAT VIC 3350 Email: mail@colinmcclelland.com.au EHPIC Consulting Group Mob. 0413 822 598 104 Wills Street Email: contact@ehpic.com.au BENDIGO VIC 3550 Fax. 5441 4881 PO Box 555 Fax. 5441 5089 GOLDEN SQUARE VIC 3555 Fax. 5441 5089 GOLDEN SQUARE VIC 3555 Ph: 9464 4617 (offices in Thomastown, Pakenham, Lara) Mob: 0458 596 025 13 Brock St Email: jared@groundscience.com.au THOMASTOWN VIC 3074 Ph. 5439 3511 PO Box 686 Mob: 0419 189 879 STRATHFIELDSAYE VIC 3551 Ph: 9336 1693 Paul Williams & Associates Pty Ltd Ph: 9336 1693 2 Argyle Place Mob: 0412 120 448 SUNBURY VIC 3429 Email: paul@rockdr.com.au Phi Jeffery, PEJ Consulting Ph. 9336 1693 21 Clarks Rd Mob. 0412 120 448 EAST KEILOR VIC 3033 Email: info@soiltest.com.au		
Colin McClelland & Associates Ph. 03 5333 3030 201 Armstrong Street North Email: mail@colinmcclelland.com.au BALLARAT VIC 3350 Mob. 0413 822 598 EHPIC Consulting Group Mob. 0413 822 598 104 Wills Street Email: contact@ehpic.com.au BENDIGO VIC 3550 Fax. 5441 4881 Geotechnical Testing Services Ph. 5441 4881 PO Box 555 Fax. 5441 5089 GOLDEN SQUARE VIC 3555 Ph. 9464 4617 Gorind Science Ph. 9464 4617 (offices in Thomastown, Pakenham, Lara) Mob: 0458 596 025 13 Brock St Email: jared@groundscience.com.au THOMASTOWN VIC 3074 Ph. 5439 3511 PO Box 686 Mob: 0419 189 879 STRATHFIELDSAYE VIC 3551 Ph. 9336 1693 Paul Williams & Associates Pty Ltd Ph. 9336 1693 2 Argyle Place Mob: 0412 120 448 SUNBURY VIC 3429 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting Ph. 9336 1693 21 Clarks Rd Mob. 0412 120 448 EAST KEILOR VIC 3033 Email: info@soiltest.com.au	Level 3, 77 Moorabool St	Email: admin@bseconsulting.com.au
201 Armstrong Street North BALLARAT VIC 3350 EHPIC Consulting Group 104 Wills Street BENDIGO VIC 3550 Geotechnical Testing Services Ph. 5441 4881 PO Box 555 GOLDEN SQUARE VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) 13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Mob. 0413 822 598 Mob. 0413 822 598 Email: mail@colinmcclelland.com.au Mob. 0413 822 598 Email: mail@colinmcclelland.com.au Email: mail@colinmcclelland.com.au Email: mail@colinmcclelland.com.au Bemail: mail@colinmcclelland.com.au Ph. 5441 4881 Fax. 5441 5089 Ph. 5441 4881 Fax. 5441 5089 Whob: 0458 596 025 Email: jared@groundscience.com.au Ph. 5439 3511 Ph. 5439 3511 Ph. 9336 1693 Mob: 0412 120 448 Email: jared@groundscience.com.au Ph. 9336 1693 Mob. 0412 120 448 Email: jared@groundscience.com.au Ph. 9336 1693 Ph. 5229 0972 47 Pakington St Email: info@soiltest.com.au		
### BALLARAT VIC 3350 #### EHPIC Consulting Group 104 Wills Street #### Email: contact@ehpic.com.au ##### Email: contact@ehpic.com.au ###################################	Colin McClelland & Associates	Ph. 03 5333 3030
EHPIC Consulting Group 104 Wills Street BENDIGO VIC 3550 Geotechnical Testing Services Ph. 5441 4881 PO Box 555 Fax. 5441 5089 GOLDEN SQUARE VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) Mob: 0458 596 025 13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd Ph. 5439 3511 PO Box 686 Mob: 0419 189 879 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Email: paul@rockdr.com.au Phi Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Email: info@soiltest.com.au Mob. 0412 120 448 Email: info@soiltest.com.au Ph: 5229 0972 Email: info@soiltest.com.au	201 Armstrong Street North	Email: mail@colinmcclelland.com.au
BENDIGO VIC 3550 Geotechnical Testing Services PO Box 555 Fax. 5441 4881 Fax. 5441 5089 Golden Square VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) Mob: 0458 596 025 13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Email: contact@ehpic.com.au Ph. 5441 4881 Fax. 5441 5089 Fax. 5441 5089 Fax. 5441 5089 Fh. 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph. 5439 3511 Ph. 5439 3511 Ph. 5439 3511 Ph. 9336 1693 Sunders Consulting Ph. 9336 1693 Mob: 0412 120 448 EAST KEILOR VIC 3033 Saunders Consulting Group Ph: 5229 0972 Email: info@soiltest.com.au	BALLARAT VIC 3350	
BENDIGO VIC 3550 Geotechnical Testing Services Ph. 5441 4881 Fax. 5441 5089 GOLDEN SQUARE VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) Mob: 0458 596 025 13 Brock St Email: jared@groundscience.com.au THOMASTOWN VIC 3074 Paladin White Pty Ltd Ph. 5439 3511 PO Box 686 Mob: 0419 189 879 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Ph: 9336 1693 2 Argyle Place Mob: 0412 120 448 SUNBURY VIC 3429 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group Ph: 5229 0972 47 Pakington St Email: info@soiltest.com.au	EHPIC Consulting Group	Mob. 0413 822 598
Geotechnical Testing Services PO Box 555 Fax. 5441 5089 GOLDEN SQUARE VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) 13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Paladin White Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group Ph: 5229 0972 47 Pakington St Emis 9444 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Phil 5439 3511 Ph. 5439 3511 Ph. 5439 3511 Ph. 5439 3511 Ph. 9336 1693 Mob: 0412 120 448 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting Ph. 9336 1693 Ph. 9336 1693 Email: info@soiltest.com.au	104 Wills Street	Email: contact@ehpic.com.au
PO Box 555 GOLDEN SQUARE VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) 13 Brock St Email: jared@groundscience.com.au THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Ph: 9336 1693 2 Argyle Place SUNBURY VIC 3429 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Email: info@soiltest.com.au	BENDIGO VIC 3550	
GOLDEN SQUARE VIC 3555 Ground Science (offices in Thomastown, Pakenham, Lara) 13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Ph: 9336 1693 2 Argyle Place SUNBURY VIC 3429 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group Ph: 5229 0972 47 Pakington St Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph. 9439 3511 Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph. 9484 9879 Email: jared@groundscience.com.au Ph: 9484 9879 Email: jared@groundscience.com.au Ph: 9484 9879 Email: jared@groundscience.com.au Ph: 9484 9879 Email: jared@groundscience.com.au Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au Ph: 9464 4617 Mob: 0458 596 025 Email: jared@groundscience.com.au	Geotechnical Testing Services	Ph. 5441 4881
Ground Science (offices in Thomastown, Pakenham, Lara) Mob: 0458 596 025 Email: jared@groundscience.com.au THOMASTOWN VIC 3074 Paladin White Pty Ltd Ph. 5439 3511 PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Ph: 9336 1693 2 Argyle Place SUNBURY VIC 3429 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group Ph: 5229 0972 47 Pakington St Email: info@soiltest.com.au	PO Box 555	Fax. 5441 5089
(offices in Thomastown, Pakenham, Lara) 13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Mob: 0458 596 025 Email: jared@groundscience.com.au Ph. 5439 3511 Mob: 0419 189 879 Ph: 9336 1693 Mob: 0412 120 448 Email: jaul@rockdr.com.au Phil Jeffery, PEJ Consulting Ph. 9336 1693 Mob. 0412 120 448 EAST KEILOR VIC 3033 Saunders Consulting Group Ph: 5229 0972 Email: info@soiltest.com.au	GOLDEN SQUARE VIC 3555	
13 Brock St THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Email: jared@groundscience.com.au Ph. 5439 3511 Ph. 5439 3511 Ph. 5439 3511 Ph. 9336 1693 Mob: 0419 189 879 Ph: 9336 1693 Mob: 0412 120 448 Email: jared@groundscience.com.au Ph. 9336 1693 Mob: 0412 120 448 Email: info@soiltest.com.au	Ground Science	Ph: 9464 4617
THOMASTOWN VIC 3074 Paladin White Pty Ltd PO Box 686 Mob: 0419 189 879 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Ph: 9336 1693 2 Argyle Place Mob: 0412 120 448 SUNBURY VIC 3429 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group Ph: 5229 0972 47 Pakington St Email: info@soiltest.com.au	(offices in Thomastown, Pakenham, Lara)	Mob: 0458 596 025
Paladin White Pty Ltd PO Box 686 Mob: 0419 189 879 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Ph: 9336 1693 2 Argyle Place Mob: 0412 120 448 SUNBURY VIC 3429 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting Ph. 9336 1693 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group Ph: 5229 0972 47 Pakington St Email: info@soiltest.com.au	13 Brock St	Email: jared@groundscience.com.au
PO Box 686 STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Mob: 0419 189 879 Mob: 0419 189 879 Ph: 9336 1693 Mob: 0412 120 448 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting Ph. 9336 1693 Mob. 0412 120 448 Email: info@soiltest.com.au	THOMASTOWN VIC 3074	
STRATHFIELDSAYE VIC 3551 Paul Williams & Associates Pty Ltd Ph: 9336 1693 2 Argyle Place Mob: 0412 120 448 SUNBURY VIC 3429 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Ph: 9336 1693 Mob. 0412 120 448 Email: info@soiltest.com.au	Paladin White Pty Ltd	Ph. 5439 3511
Paul Williams & Associates Pty Ltd 2 Argyle Place SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Ph: 9336 1693 Mob. 0412 120 448 Ph: 9336 1693 Mob. 0412 120 448 Email: info@soiltest.com.au	PO Box 686	Mob: 0419 189 879
2 Argyle Place SUNBURY VIC 3429 Email: paul@rockdr.com.au Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Mob: 0412 120 448 Email: info@soiltest.com.au	STRATHFIELDSAYE VIC 3551	
SUNBURY VIC 3429 Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Email: paul@rockdr.com.au Ph. 9336 1693 Mob. 0412 120 448 Ph. 5229 0972 Email: info@soiltest.com.au	Paul Williams & Associates Pty Ltd	Ph: 9336 1693
Phil Jeffery, PEJ Consulting 21 Clarks Rd EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Ph. 9336 1693 Mob. 0412 120 448 Ph. 5229 0972 Email: info@soiltest.com.au	2 Argyle Place	Mob: 0412 120 448
21 Clarks Rd Mob. 0412 120 448 EAST KEILOR VIC 3033 Saunders Consulting Group Ph: 5229 0972 47 Pakington St Email: info@soiltest.com.au	SUNBURY VIC 3429	Email: paul@rockdr.com.au
EAST KEILOR VIC 3033 Saunders Consulting Group 47 Pakington St Ph: 5229 0972 Email: info@soiltest.com.au	Phil Jeffery, PEJ Consulting	Ph. 9336 1693
Saunders Consulting Group 47 Pakington St Ph: 5229 0972 Email: info@soiltest.com.au	21 Clarks Rd	Mob. 0412 120 448
47 Pakington St Email: <u>info@soiltest.com.au</u>	EAST KEILOR VIC 3033	
	Saunders Consulting Group	Ph: 5229 0972
WEST GEELONG VIC 3218	47 Pakington St	Email: info@soiltest.com.au
	WEST GEELONG VIC 3218	

22 Nolan Street / PO Box 194, Maryborough VIC 3465 • Customer Service: 03 5461 0610 • Email: mail@cgoldshire.vic.gov.au